

ERRATA to the 2015 NSPC First Printing

April 15, 2015

Page 180, Section 7.10.6: Item "f" was removed in error and has been re-inserted in the Second Printing.

Insert 2012 NSPC version of item "f" as follows:

f. Shower pan liners shall slope to the shower drain outlet and be sealed to the weep holes in the drain fitting. The liner shall provide a water-tight basin up to the overflow elevation of the shower floor.

Change the 2015 NSPC First Printing item "f" to item "g".

g. Shower pan liners shall be tested for leakage. There shall be no leakage on the floor surrounding the shower pan for a period of not less than 15 minutes.