

# Errata for 2021 National Standard Plumbing Code–New Jersey Edition 1<sup>st</sup> Printing

The following is a change that we found after the first printing of the *2021 National Standard Plumbing Code, Illustrated–New Jersey*. We do encourage you to make a note in your code book to ensure that the change is reflected. Thank you.

## **SECTION: 7.11.4 Service Sinks and Mop Receptors**

Change paragraph b.) to read as follows:

b. Service sinks and mop receptors shall not be installed where walls and floors are not waterproof and do not have a smooth, readily cleanable surface. Refer to the International Building Code, Section ~~1209.2.2~~ 1210.2.2.

## **TABLE 10.19: Sizing of Residential Water Softeners**

Correct the number of bathroom groups served to the following:

Required Size of Softener Connection (in.)	Number of Bathroom Groups Served <sup>1</sup>
3/4	Up to <del>22</del> 2 <sup>2</sup>
1	Up to <del>43</del> 4 <sup>3</sup>

Updated 9/4/2024